

JACKSON HOLE AIRPORT	FIELD
CONDITION & FRICTION MEASUREMENT	
REPORT	

SARSYS SAAB FRICTION TESTER (SFH)

DATE: 3/8/2010

TIME: 6:15

FIELD CONDITIONS

RUNWAY 19		RUNWAY 01	
TOUCHDOWN =		TOUCHDOWN =	
MID =		MID =	
ROLLOUT =		ROLLOUT =	
RUNWAY 01/19 CONDITON N.O.T.A.M.			
TAXIWAY N.O.T.A.M.			
TAXIWAY A MU:	A1 - A2	A2-A3	A3 - A4
RAMP N.O.T.A.M.			
RAMP MU:	COMMERCIAL	GENERAL AVIATION	
COMMENTS			
Runway, taxiway, ramps and laterals bare.			
REPORTED TO:		LOCKHEED MARTIN, PRESCOTT HUB 1-877-4-US-NTMS	
FSS	<input checked="" type="checkbox"/>	INITIAL <u>Prior CZ</u> TOWER	<input checked="" type="checkbox"/>
JHAB	<input checked="" type="checkbox"/>	JHAV	<input checked="" type="checkbox"/>
WWFS	<input checked="" type="checkbox"/>	SWA	<input checked="" type="checkbox"/>
UNITED	<input checked="" type="checkbox"/>	NWA	<input type="checkbox"/>
		LYNX	<input type="checkbox"/>

REPORTING OFFICER: P. Walters

TIME: 6:15